



Early Journal Content on JSTOR, Free to Anyone in the World

This article is one of nearly 500,000 scholarly works digitized and made freely available to everyone in the world by JSTOR.

Known as the Early Journal Content, this set of works include research articles, news, letters, and other writings published in more than 200 of the oldest leading academic journals. The works date from the mid-seventeenth to the early twentieth centuries.

We encourage people to read and share the Early Journal Content openly and to tell others that this resource exists. People may post this content online or redistribute in any way for non-commercial purposes.

Read more about Early Journal Content at <http://about.jstor.org/participate-jstor/individuals/early-journal-content>.

JSTOR is a digital library of academic journals, books, and primary source objects. JSTOR helps people discover, use, and build upon a wide range of content through a powerful research and teaching platform, and preserves this content for future generations. JSTOR is part of ITHAKA, a not-for-profit organization that also includes Ithaka S+R and Portico. For more information about JSTOR, please contact support@jstor.org.

Mosquito-Eradication Measures at Honolulu.

The following statement of the work of mosquito destruction at Honolulu was received from Passed Asst. Surg. McCoy, who is detailed as sanitary adviser to the governor of the Territory of Hawaii:

Mosquito-eradication measures conducted at Honolulu from Mar. 25 to 30, 1912, both inclusive.

Inspections of—	Total inspections.	Larvæ found in.	Ordered cleaned.	Oiled.	Drained.	Emptied.	Filled.	Ordered repaired.	Screened.	Stocked with mosquito fish.
Gutters, house.....	680	7	49					8		
Gutters, street.....	311	32		77						
Standing water.....	394	32		70	14					
Cesspools.....	975	43		71				26		
Privy vaults.....	1,432	24		35				16		
Holes and low places.....	662	169		195	4		79			5
Catch basins.....	425	39		145						
Leaky fixtures.....	49	1						35		
Water-holding plants.....	149	5	5							
Swamps.....	137	11	7	2						2
Ponds.....	64	1		1						
Troughs and tanks.....	335	18		1		30				3
Tubs or other receptacles.....	1,086	142	1	11		451				
Tin cans, bottles.....	1,536	118				766				
Water barrels.....	859	41	25			61			115	30
Vacant houses.....	223									

Number of loads of tin cans collected..... 32

Number of rice plantations inspected..... 15

Summary of Reports, November, 1911-March, 1912.

Inspections of—	Total inspections.	Wigglers found in.
Gutters, house.....	30,591	1,074
Gutters, street.....	4,146	399
Standing water.....	13,181	2,031
Cesspools.....	14,306	681
Privy vaults.....	18,472	456
Holes and low places.....	11,824	1,898
Catch basins.....	7,997	373
Leaky fixtures.....	3,432	44
Water-holding plants.....	30,928	1,641
Swamps.....	1,336	249
Ponds.....	1,708	104
Troughs and tanks.....	4,055	394
Tubs or other receptacles.....	10,939	1,208
Tin cans, bottles.....	259,824	2,967
Water barrels.....	7,305	1,268
Vacant houses.....	1,089	84
Yards.....	2,700	50
Grease traps.....	863	2
Washhouses.....	129	5
Holes in trees.....	10,771	166
Rice plantations.....	54	54

Loads of tin cans collected..... 224

Legal notices to abate nuisances served..... 616

Nuisances abated..... 525

Swamp land drained..... acres... 30

Ditches dug..... miles (estimated)... 20